

71 100

FIG. 2







FIG. 3


## BEST AVAILABLE COPY


FIG. 4 User Interface Example












## BEST AVAILABLE COPY


FIG. 9 Timing Report Table


700 ¥

704

			profit was a second	7.2	en e			<b>a</b> t
🍣 ing aken Compilation Repos:					011 <b>111</b>			<b>J</b>
Compilation Report			ক ্রিবার্ট্রামী, <sub>বি</sub> শ্লোর্টান্ড					H
Legal Notice		Source Name:	Pin Location	Pin Names	Enable	Status	Delay (na)	II
Flow Summary	133	reg2	Pin_H35	sp2	On	Routed	8.786 ns	IΙZ
	2	reg1	Pin_U26	sp1	On	Routed	8.747 ns	176:
Flow Elapsed Time 19	2 一個	pin_o0	Pin_P27	sp_test	On	Routed	5.808 ns	
Flow Log	1	reg0	Pin_F35	sp0	0n	Routed	Registered	רוו
☐ ☐ Analysis & Synthesis	5	reg3	Pin_H34	sp3	On	Routed	Registered	1
日	Ē	reģ4.	Pin_U27	sp4	On	Routed	Registered	776
Assembler 707	9	reg5	Pin_T27	sp5	On	Routed	Registered	11 710
Timing Analyzer Settings	18	reg6	Pin_G35	sp6·	On	Routed	Registered	<b>                                     </b>
Timing Analyzer Summary	io.	reg7	Pin_G34	sp7	On	Routed	Registered	制人
Clock Settings Summary		)	)	)	7	7	)	13
Clock Setup: 'clk'		(		(	l		7`~	1
tsu		730	732	734	736	738	739	1
	171	130		,	, , ,			1
								if
Source to Output D	elays							1
<b>₽</b>		•						4
Minimum too	12		711					
		716						
Timing Analyzer INI Usage								
Timing Analyzer Messages								1
								H
<b>J</b>	1/2		<del></del>				. <del></del>	










FIG. - 12B